

CRS BULLETIN

CRS, Incorporated 4851 White Bear Parkway St. Paul, Minnesota 55110-3325 • 651/294-2700 • 651/294-2903

DATE: January 7, 2014
TO: SAM4s SPS-5X0 Dealers
RE: SAM4s SPS-5X0 Bootrom Update

CRS has posted new SAM4s SPS-500 software. Software and instructions can be downloaded from the Dealer Area SPS-500 support page.

Priority: Bootrom update to v 1.14+ must be done at the same time with updates to XLIB version 1.11 and Application version 1.00n (Apr. 7).

Notice: NEVER downgrade the BOOTROM version.

Update Instructions

Detailed instructions are included in the upgrade zip package.

Bootrom Version History

Version 1.20 (6/28/2013)
Version upgrade to accommodate a hardware change.
Version 1.19 (12/12/2012)
Minor verbiage change.
Version 1.18 (6/26/2012)
Added DISABLE AGING TEST option to the special password
Version 1.17 (3/17/2011)
Correct logo download error on slow flash
Version 1.16 (1/6/2011)
Prevent bootrom downgrade
Version 1.15 (11/15/2010)
Adjust LCD parameter for new LCD.
Version 1.14 (2/23/2010)
Added ability to update XLIB alone.
Version 1.13 (11/25/2009)
Added TFTP logo download feature.
Fix garbage screen on booting.
Version 1.12 (10/10/2009)
Add checksum comparison after COPY ALL.
Add to check micom checksum.
Version 1.11 (9/16/2009)
Add a menu to define special character for rear display.
Change rear display test process.
Change Modem test phone number.
Set default LCD backlit to 8 (center).
Version 1.10 (8/20/2009)
Add Modem test for Korean version. \ Print Korean receipt sample for Korean version.